

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

HP1088
ENE
> 1
1.428 mi.
7540 ft.

SOIL
1515 AVE Z
BROOKLYN, NY

NY Spills S118707310
N/A

Site 1 of 2 in cluster HP

Relative:
Higher

Actual:
23 ft.

SPILLS:

Name: SOIL
Address: 1515 AVE Z
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1604520 / 2017-01-30
Facility ID: 1604520
Facility Type: ER
DER Facility ID: 485095
Site ID: 531030
DEC Region: 2
Spill Cause: Other
Spill Class: C3
SWIS: 2401
Spill Date: 2016-08-04
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 2016-08-04
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2016-08-04
Spill Record Last Update: 2017-01-30
Spiller Name: Not reported
Spiller Company: OCTOBER SKY
Spiller Address: Not reported
Spiller Company: 999
Contact Name: GEORGE KRASANAKIS
DEC Memo: "8/4/16 - Obligado - Desk Duty - I spoke with George Krasanakis. They found contamination in 3 pits they are excavating for dry wells as part of redevelopment for commercial building with a parking garage. I told him contaminated soil needs to be excavated, stockpiled and properly disposed of at a permitted facility. I assigned the spill to Ryan Piper to work with the developer. According to PBS this site had 10 550s under PBS #2-600672 listed as closed prior to 1991. The site had 2 historic spill numbers, all closed. 9209311 and 0207183 1/5/17- DEC Piper spoke with George K. He had soils tested and will send analyticals to me via email for review. 1/30/2017- DEC Piper reviewed documents. according to notes of spill 9209311 - 3,500 tins of contaminated soils were removed along with tanks. Spill was closed. This current development plans for the site require slab on grade construction with no basement and planned excavation not to exceed 2' bgs. Excavated soils for drywells were taken to Richmond Recycling in Staten Island. Manifest totaling approx. 1000 tons of soil were received. As per DEC Austin, This spill administratively closed based on remediation of spill 9209311."
Remarks: "Caller advised found contamination in soil during excavation of a parking lot. Caller advised that in 2004 the property was remediated

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

with accordance to SPILL# 92-09311. Caller advised that he was not the owner of the property in 2004 and bought the property under the guise that the property had been remediated."

All Materials:

Site ID:	531030
Operable Unit ID:	1279815
Operable Unit:	01
Material ID:	2284905
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported